State of Wisconsin

County of Languade

· SS.

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. V. 3

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

pipe with brass cap الله

Rock with X 10 Links East

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

6" Cherry N46E 8.5 Ft. 7" Cherry NO 16.6 Ft. 6" Spruce N54W 21.7 Ft.



Dated at / Antiro	, Wis., this	8th	day of	April	, 19. <u>79</u>
Signature Cognional Sh	llely Title	Reg. Surv	Jeyor	Registr	ation No. S-685
Dated at Antigo Signature (County Surveyor, R Office of Register of Deeds, Count	egistered Land Surve	yor, or other du	ly authorized off	icial) , I hereby cer	tify that the within
instrument was filed in this office f	or record on the		day of		, 19
ato'clock M.					
(Register o	Deeds)				