O = Corner	monument	restored.
------------	----------	-----------

CERTIFIED LAND CORNER RESTORATION

Index No. 4-5

History of original corner establishment:

4" Br:ss cap set in the 1930 resurvey

Description of corner evidence found:

See above

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

8" Red Maple N50W 23.5 Ft.

Fed Maple S3W 38.9 Ft.

6" Red Maple S38W 52 Ft



(Register of Deeds)

By......Deputy