U.S. PUBLIC LAND SURVEY MONUMENT RECORD


NOTE: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A—E 7 .08 U.S. Public Land Survey Monument Record (3)(a)(b)(c)(d)(e)(f) (g)(h)(i). An additional sheet may be added if necessary to conform with said regirements.

(a)Corner location: Township 34_North

Range_10_East/West

Town/City/Village ___ELCHO_____

County __LANGLADE _____



(b)(f)(g)(h) Description of monument found at this corner and if it was accepted, state all evedence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. Ifnot accepted or if nothing was found, state evidence used as basis for establishing location. If reestablished through lost corner propotionate methods, indicate all monuments, distances and directions used to establish. Indicate type of monument found or set and sign post.


JULY, 1865 - JAS T. NOWLIN, DEPUTY SURVEYOR, VAR. N6'50'E, 40 CHAINS SET 1/4 SECTION POST, B.T.- 10" BIRCH N.15'E, 20 LINKS, 6" HEMLOCK S20'E, 30 LINKS.

1936 - D. A. HINTZ, E. F. KOWALKE, C. W. BORTH - BEARED N4'00'E, 47.86 CHAINS TO THE ORIGINAL 1/4 CORNER. THEY FOUND AN ORIGINAL ROTTEN BIRCH B.T. N15'E, 20LINKS. MADE NEW B.T's:

6" MAPLE N83"W, 40.6 LINKS 5" BIRCH S65"E, 17.7 LINKS

7-26-99 - NICOLET SURVEYING- SEARCHED RECOVERY AREA AND FOUND D. A. HINTZ's 4" CAPPED IRON PIPE ESTABLISHED NEW TIES.

(c)(d)(e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed corner.



(i) I, Deven Vanden Heive (type or print name) certify that the corner location on this record was determined by me of under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

7/26/99 Date



√, √,