

CERTIFIED LAND CORNER RESTORATION

Index No. **21.7**

**34-10**

State of Wisconsin }  
County of Lanai } ss.

I, Raymond J. Halliday, do hereby certify that on the 29th day of April, 1928, I found evidence of the North 1/4 W.C. corner of Section 5 Township 33, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....  
.....  
.....

History of original corner establishment:

Corner established in 1938 Re-survey

Description of corner evidence found:


4 inch Iron Pipe with Brass Cap  
County Highway T 23 Lks North Runs East + West



Description of monument and accessories I established to perpetuate the original location of this corner.

- New B.T.S
- Red Maple 7" S30E 20 FT. 9 inches
- Red Maple 4" S6W 19 FT. 9 inches
- Red Maple 6" S31W 24 FT. 6 inches

FORM 5075 W. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 29th day of April, 1928.

Signature Raymond J. Halliday Title Registered Land Surveyor Registration No. 5-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy