

CERTIFIED LAND CORNER RESTORATION

Index No. A-6-7
33-10


State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallsy, do hereby
certify that on the 28th day
of July, 1979, I found
evidence of the East Meander
corner of Fish Lake in Section 5 & 32
Township 33 & 34, North, Range
10E, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:

.....
.....
.....

FORM 985 R. E. MILLER CO. - MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Corner set in the 1930 resurvey.


Description of corner evidence found:

4" pipe with brass cap

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

- 7" Hemlock S26E 8' 8"
- 7" Hemlock S 7W 8' 6"



Dated at Antigo, Wis., this 28th day of July, 1979.

Signature Raymond J. Hallsy Title Reg. Surveyor Registration No. S685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within
instrument was filed in this office for record on the..... day of....., 19.....
at..... o'clock..... M.

.....
(Register of Deeds)
By..... Deputy