

CERTIFIED LAND CORNER RESTORATION

Index No. A-5-6
33-10


State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 28th day of July, 19 79, I found evidence of the West meander corner of Section 5 & 32 Township 33 & 34, North, Range 10E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

FORM 985 H. C. MILLER CO. MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Corner set in the 1930 resurvey.


Description of corner evidence found:

Hub with nail on top in corner location				
Original BT	10"	White Birch	N38 W	6 Links
1930 BT's	16"	Hemlock	N1 1/2 W	31.8 Links
"	15"	Hemlock	S11 E	2 1/4 Links

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap
New BT's

12"	White Birch	S4W	13' 4"
10"	Hemlock	N70W	6' 5"
11"	Hemlock	N16E	4' 10"



Dated at Antigo, Wis., this 28th day of July, 19 79.

Signature Raymond J. Hallisy Title Reg. Surveyor Registration No. S685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy