


CERTIFIED LAND CORNER RESTORATION

Index No. 2-15


State of Wisconsin }
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 20th day of October, 1980, I found evidence of the Quarter corner of sections 34 and 3 Township 33 and 34, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Original corner established by J.L. Nowlin, deputy surveyor, in 1865 from which Tamarack 6" bears N49°W 95 links and Tamarack 6" bears S8°E 46 links. In 1937 Langlade County surveyors recovered B.F. Dorr's re-established 1/4 corner.

Recovered old B.T.'s:

- Tamarack 4" N70°W 24-1/2 links
- Tamarack 4" S20°W 31-1/2 links

Description of corner evidence found:

Recovered a 4" iron pipe filled with concrete and capped with a 4" brass cap, stamped:

O.B.T.'s - gone

Langlade County
T34N R10E
1/4S +³⁴/₃
T33N
11-22-37

Description of monument and accessories I established to perpetuate the original location of this corner.

Drove stakes around monument for support.

Marked N.B.T.'s:

- Black Spruce 3" S59°E 12.44 feet
- Black Spruce 3" S25°W 19.43 feet scribed B.T.
- Black Spruce 4" S67°W 17.31 feet

Dated at Rhinelander, Wis., this 23rd day of February, 1981

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy