0	=	Corner	monument	restored
---	---	--------	----------	----------

## CERTIFIED LAND CORNER RESTORATION

Index No. ¥-15

History of original corner establishment:

No evidence of any previous corner.



Description of corner evidence found:

Corner established by traverse and computation.

From C 1/4 corner section 34 to 1/4 corner between sections 34-34-10 and 3-33-10 total distance is 3224.438 feet.

Set SC 1/16 1612.219 feet intermediate at bearing S3-24-50E.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap, stamped:

Monument projects 12" above ground.

Marked NBT's -

Maple 5" S48°W 13.23 feet Maple 7" N25°E 40.20 feet

Hemlock 12" S46°E 23.12 feet all scribed 1/16 BT.

T34N R10E sc  $1/16 \stackrel{S}{-} 1^{34}$ 

S1537-1980

Dated at Rhinelander	, Wis., this4th	day of Decer	nber , 19 80
Signature Daniel K. Pleas (County Surveyor, Reg	Title Register	ed Land Surveyor	Registration No. S-1537
Office of Register of Deeds, County instrument was filed in this office for at	of	, I he	ereby certify that the withir
(Parister of I	Operis)		