

CERTIFIED LAND CORNER RESTORATION

Index No. Y-14


State of Wisconsin }  
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 18th day of September, 1980, I ~~found~~ established ~~the~~ SW 1/16 corner of Section 34 Township 34, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....

FORM 983 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:  
No evidence of any previous corner.



Description of corner evidence found:

Corner established by subdividing the SW 1/4 section 34 - T34N R10E.  
Location of SW 1/16 corner is N 2-26-11W 1547.254 feet of W 1/16 corner between sections 34-34-10 and S2-26-11E 1547.243 feet of WC 1/16 section 34.

Description of monument and accessories I established to perpetuate the original location of this corner.  
Set a 1-1/2" I.D. iron pipe with screw-on brass cap, stamped:  
Monument projects 8" above ground.

Marked NBT's -  
Maple 6" S35W 24.40 feet  
Maple 5" S56E 17.0 feet  
W. Birch 8" S12E15.15 feet  
scribed 1/16 BT

T34N R10E  
SW 1/16 S + 34  
S1537-1980

Fence corner bears S48W 9.00 feet from corner position.

Dated at Rhineland, Wis., this 4th day of December, 1980

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. S-1537  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By \_\_\_\_\_ Deputy