

CERTIFIED LAND CORNER RESTORATION

Index No. X-17

State of Wisconsin }  
County of Langlade } ss.

I Daniel K. Pledger, do hereby certify that on the 19th day of September, 1980, I found evidence of the Quarter corner of Sections 34 and 35 Township 34 North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....

History of original corner establishment:

Original corner established by J.L. Nowlin, deputy surveyor, in 1865 from which Birch 12" bears N80°W 20 links and Hemlock 8" bears N85°E 10 links. In 1937 Langlade County surveyors recovered re-established 1/4 corner by B.F. Dorr, county surveyor, from which Norway Pine 14" bears N 19-1/2° W 17-3/4 links.

Description of corner evidence found:

Recovered a 4" iron pipe with 4" brass cap - stamped:  
Projecting 8" above ground.  
OBT's - Norway 14" N19°W 17.75 links  
stump scribed 1/4S B.T.  
White Pine N14°E 18.78 links  
scribing grown over

Langlade County  
T34N R10E  
1/4 S34 | 35  
11-10-37

Description of monument and accessories I established to perpetuate the original location of this corner.


Monument left as recovered.

Marked NBT's:


Maple 6" N66°W 14.70 feet  
Maple 6" N62°E 10.70 feet scribed 1/4 B.T.

FORM 983 H. C. MILLER CO., MILWAUKEE

T34N R10E



○ = Corner monument restored.



Dated at Rhinelander, Wis., this 4th day of February, 1981

Signature Daniel K. Pledger Title Registered Land Surveyor Registration No. 1537  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy