location of this corner.

State of Wisconsin

County of Langlade

I Daniel K. Pleoger do hereby

certify that on the 8th day

corner of section 34 North, Range 10 East Fourth Principal Meridian, as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original


SS.

CERTIFIED LAND CORNER RESTORATION

Index No. W-14

History of original corner establishment:

No evidence of any previous corner



Description of corner evidence found:

Corner established by subdividing the NW 1/4 section 34 T34N R10E. Location of NW 1/16 corner is S2-17-35E 1450.336 feet of W 1/16 corner between sections 27-34 and N2-17-35W 1450.337 feet of WC 1/16 section 34.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap, stamped: Projecting 12" above ground.

Marked NBT's -

Tamarack 8" S86W 23.78 feet

Tamarack 6" N48E 44.68 feet, scribed 1/16 BT Tamarack 4" S58W 3.80 feet, scribed 1/16 BT

T34N R10E NW 1/16 S + 34

S1537-1980

Dated at Rhinelander , Wis., this 26th day of November 19 80

Signature Daniel L. Pleogra Title Registered Land Surveyor Registration No. S-1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

(Register of Deeds)

By......Deputy