


CERTIFIED LAND CORNER RESTORATION

Index No. X-21


State of Wisconsin }
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 16th day of September, 1980, I found evidence of the Quarter corner of Sections 35 and 36 Township 34 North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



FORM 983 N. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Original survey by J.L. Nowlin in 1865 had 1/4 corner in pond. In 1882 B.F. Dorr, county surveyor, set 1/4 corner from which Tamarack 3" bears S32-1/2°W 48 links. Langlade County surveyors in 1937 recovered B.F. Dorr's corner and tamarack B.T. S 32-1/2° W 48 links.

Description of corner evidence found:

Recovered an old 4" squared cedar post on west edge of pond. Corner sets 4.0 ft. west of water.
Post is very old - unable to see any scribed marks on it.

OBT - Tamarack 3" S32°W 48.0 links
No evidence of this B.T.

Description of monument and accessories I established to perpetuate the original location of this corner.

Removed old wood post and replaced with a 2-1/2" iron pipe with screw-on brass cap - stamped:

Projecting 8" above bog.

Marked NBT's:

Tamarack 3" S24°W 9.38 feet
Tamarack 3" S66°W 12.95 feet scribed 1/4 - BT
Tamarack 5" N68°W 53.56 feet

T34N R10E
1/4 35 + 36
S1537-1980

Dated at Rhinelander, Wis., this 18th day of February, 1981

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy