


CERTIFIED LAND CORNER RESTORATION

Index No. X-19


State of Wisconsin } ss.
County of Langlade }

I Daniel K. Pleoger, do hereby certify that on the 31st day of October, 19 80, I found evidence of the C 1/4 corner of Section 35 Township 34, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



T34N R10E



○ = Corner monument restored.

History of original corner establishment:

Corner established in 1882 by B.F. Dorr, County Surveyor, from which pine stump 24" bears S72°W 22 links and Maple 12" bears S61-1/2°E 18 links.

Description of corner evidence found:

Recovered upper portion of old squared cedar post in old rotted pine stump. Dorr's note states he set his corner in a 27" pine stump. O.B.T. pine stump 24" bears S72°W 22 links - now somewhat rotted. Fence lines run north-south-east and west from old corner on subdividing section 35. Our C 1/4 corner position falls N 32-55-18 E 21.35 feet of Dorr's corner. Used Dorr's C 1/4 corner to establish all interior corners in section.

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced old post with a 2-1/2" iron pipe with screw-on brass cap - stamped:

Marked NBT's:

Maple 6" N16°E 28.85 feet
Maple 7" N80°W 2.12 feet scribed C 1/4-B.T.
Maple 6" S32°W 32.13 feet

T34N R10E
C 1/4 S 35
S1537-1980

Dated at Rhinelander, Wis., this 25th day of February, 19 81.

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy