State of Wisconsin ss.	Н
I. WILLIAM F. KELLY, do hereby certify that on the	D
location of this corner.	
Resident witnesses:  D. FRITZ	
	D
	N
T. 34N, -R.IIE.	1
2	
	D
281.23 <sup>1</sup>	Si
	O: in
	at

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION	SCONS	Index No. C - 18219
tory of original corner establishment:	WILLIAM F. KELLY	34-11

istory

S1098 William S. Kelly 6/22/76

escription of corner evidence found: FOUND 1/2" IRON PIPE IDENTIFIED BY RESIDENT WITNESS AS MEANDER CORNER ON THE EAST SHORE OF UPPER POST LAKE. SAID PIPE MARKING THE S.W. CORNER GOV'T LOT 5, SECTION 2 - T. 34N. - R.II E.

\$ B.T. 14" WHITE PINE WITH + MARK AT BASE. escription of monument and accessories I established to perpetuate the original location of this corner. SET 2" PIPE WITH BRASS CAP. PUNCH MARK IN CENTER OF CAP. MARKED NEW WITNESS TREES. 2" B.I.P. WITH BRASS CAP B.T. - 24" WHITE PINE WITH OLD BLAZE MARK, NEW + MARK AT BASE. 580% - 3.50' B.T. 26" WHITE PINE WITH & MARK AT BASE. , Wis., this. 3RO.day of JUNE , 19.76... Title RE6/STERED LAND SURVEYOR Registration No. 5/098 (County Surveyor, Registered Land Surveyor, or other duly authorized official) fice of Register of Deeds, County of....., I hereby certify that the within strument was filed in this office for record on the day of 

(Register of Deeds)

By......Deputy