
State of	Wisconsi	n ]
State of County of <u>AM</u>	GLADE	
I., ROBERT certify that on th	J. Poss	, do hereb
certify that on th	ne380	da
of JULY		19.63, I foun
evidence of the	ONE - Q UI	ARTER
corner & RATW	FEN SEC. 2	2 E 13

Township 34, North, Range // EAST Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:	



O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

POSS 5-0001

94-11

Description of corner evidence found:

2" PIPE SIMILAR TO ALL OTHERS FOUND IN THE AREA.

Description of monument and accessories I established to perpetuate the original location of this corner.

/"PIPE WITH 4" BRASS CAP SET IN 6"DX42, CONCRETE.
MK'D LANGLADE COUNTY 14 COR SEC.3; SEC.2
TN 34 N RILE. XI . S.E. COR. FR. RES. N9°W 95.0'

X 2 POWER POLE # 3411 - 2W6 N 4°E 55.8' X3 POWER POLE # 3411- 2W4 52 E 37.1' X4 W.PINE 12"N56W 38.25' NOT BLAZED

COMPASS ERRATIC - A/C PROX. TO POWER LINE.

Dated at ELCHO, Wis., this 3RD day of July , 1967...

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

instrument was filed in this office for record on the \_\_\_\_\_\_day of \_\_\_\_\_\_\_, 19\_\_\_\_\_\_ 

(Register of Deeds)

By......Deputy