
O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:



Description of corner evidence found:

FOUND 2" IRON PIPE SIMILAR TO OTHER STAKES; NO OTHER IDENTIFICATION.

Description of monument and accessories I established to perpetuate the original location of this corner.

SET I DIPE WITH 4 DRASS CAD MIXED IN G"X 42" CONCRETE. TREES NOT BLAZED OR SCRIBED (FRONT YARD) X2: SE COR. MET. BLOG ON CONC. SLAB N 78°W 34 X3 NE COR I SF RES. SI2°W. 37.9; X4: NW COR I X5: N 36°W 30.4' TO 24" NWY PINE; X6: 10"No N20°E 11.1' & 12" JACK PINE N 21°E 8.0'; X7: NWY	MEA COR SEC. 3 - SEC .5' T 34 N R II E I- 5-FRES S35°W 47.8	C2 Top of	LOKE NO TO
Signature (County Surveyor, Registered Land Surveyor, or other Office of Register of Deeds, County of instrument was filed in this office for record on the at o'clock M.		., I hereby certify t	hat the within
(Register of Deeds)			