CERTIFIED LAND CORNER RESTORATION

Index No. E-6

History of original corner establishment:

No record of any previous survey.

Description of corner evidence found:

No evidence of any corner recovered.

Corner established by traverse and computation. Ran traverse from 1/4 corner between sections 5 and 8 to section corner 5, 6, 7 and 8. Computed distance - 3102.86 feet at bearing N 87° 29' 51" W.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" iron pipe with screw-on brass cap - stamped:

Monument projects 12" above ground.

Marked NBT's -

B.Spruce 6" S36°E 69.45' scribed 1/16 BT. W.Birch 6" N68°E 29.85' scribed 1/16 BT. T34N R11E
W $1/16 \frac{s}{s} + \frac{5}{8}$ S498 - 1980

Dated at Rhinelander , Wis., this 27th day of March , 19.80 ...

Signature Siljo Thaman. Title Registered Land Surveyor Registration No. S-498 County Surveyor, Registered Land Surveyor, or other duly authorized official)

at...... .o'clock..... M.

(Register of Deeds)

By......Deputy