CERTIFIED	LAND	CORNER	RESTORATION

Index No.D-6

History of original corner establishment:

Description of corner evidence found:

No evidence of any corner recovered. Corner established by traverse and computation. Computed distance from WC 1/16 section 5 to W 1/16 between sections 5 and 8 is 2635.42' at bearing S 5° 15' 10" W. Computed location of SW 1/16 is 1317.72 feet S 5° 15' 10" W of WC 1/16 and 1317.70' N 5° 15' 10" E of W 1/16 between sections 5 and 8. Ran traverse to and set WC 1/16 at 1317.72' from W 1/16 and 1317.70 from WC 1/16.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap, stamped: Monument projects 18" above ground.

Marked NBT's Maple 5" S82°W 18.52'
Maple 6" N64°E 55.25'

both scribed 1/16 BT.

T34N R11E SW $1/16 \stackrel{S}{+}^{5}$ S498 - 1980

Dated at Rhinelander , Wis., this 18th day of April , 1980

Signature Lill Handler . Title Registered Land Surveyor Registration No. S-498

(Register of Deeds)

By.....Deputy