O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

Index No. C-9

History of original corner establishment:

Description of corner evidence found: No evidence of any corner recovered. In order to establish this 1/4 corner we projected a line east from the 1/4 corner between sections 5 and 6 along the south edge of a very old and well deliniated field a distance of about 2,000 feet. Then continued to the intersection of section line between sections 4 and 5. All indications are that the C 1/4 section 5 and the 1/4 corner between sections 4 and 5 were evident when this field was cleared. Adjacent property owners have accepted this line for many years. Corner sets S 4° 23' 20" W, 2,847.134 feet from section corners 4, 5, 3 and 33 and N 4° 23' 20" E, 2,603.59 feet from section corners 4, 5, 8 and 9.

Set a 2-1/2" iron pipe with screw on brass cap, stamped:	
Marked NBT's -	
Sugar 4" S50 <sup>O</sup> F 30 151	T3/N P11F

Description of monument and accessories I established to perpetuate the original location of this corner.

green up				
		S50°E		T34N R11E
		S24 <sup>O</sup> E		1/4 4+5
		s7 <sup>0</sup> ₩		1/4 —
Maple	5"	N27 <sup>O</sup> W	32.59'	S498 <b>-</b> 1980
all	scri	bed 1/4	BT.	

Dated at	Rhinelander	, Wis., this.	7th	day of	April	19.80
Signature	Thilip Hansen. (Jounty Surveyor, Register	Title ed Land Surve	Registered	Land Surveyor	Registration	No. S-498
Office of R	egister of Deeds, County of was filed in this office for rec		Langlade	,	I hereby certify th	hat the within
at	o'clock M.					
•	(Register of Deeds	s)				