O = Corner mo	nument restored
---------------	-----------------

CERTIFIED LAND CORNER RESTORATION

Index No. C-7.

History of original corner establishment:

Description of corner evidence found:

No evidence of any corner recovered. Corner established by traverse and computation. Ran traverse from N 1/4 to S 1/4 and from W 1/4 to E 1/4 to establish corner. Computed distances, 2,734.258', S 3° 41' 43" W of N 1/4 and 2,618.23', N 3° 41' 43" E of S 1/4; 2,764,19', N 86° 55' 38" W of E 1/4 and 2,959.104' S 86° 55' 38" E of W 1/4.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 2-1/2" iron pipe with screw on brass cap, stamped: Monument projects 16" above ground. Marked NBT's -

Maple 9" S23°E 38.50' Sugar 5" N9°W 15.40' W. Ash 8" N81°W 17.50' all scribed C 1/4 BT. T34N R11E C 1/4 S+5 S498 - 1980

(Register of Deeds)

By......Deputy