## CERTIFIED LAND CORNER RESTORATION

Index No. C-6

History of original corner establishment:

Description of corner evidence found:

both scribed 1/16 BT

No records of any corner recovered. Corner established by traverse and computation. Distance and bearing from W 1/4 to C 1/4 corner is  $2959 \cdot 104$  feet at S  $86^{\circ}$  55' 38" E. Set WC 1/16 at  $1479 \cdot 55$  feet intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" ID iron pipe with screw-on brass cap, stamped:
Monument projects 18" above ground.

Marked NBT's 
Maple 8" N30°W 16.68 feet

Maple 5" S59°E 25.63 feet

W

T34N R11E

WC  $1/16 \stackrel{S}{+} \stackrel{5}{-}$ S498 - 1980

(Register of Deeds)

.....Deputy