O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Description of corner evidence found:

No evidence of any corner recovered.

Corner established by traverse and computation. Ran traverse from 1/4 corner between section 5 and 6 to section corner 5, 6, 7 and 8. Computed distance is 2654.54 feet at bearing S 6° 47' 19" W.

Set S 1/16 at 1327.27 feet intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" ID iron pipe with screw-on brass cap, stamped:

Monument projects 8" above ground.
Marked NBT's - B.Ash 5" N50 E 33.11 feet

B.Ash 5" S51°E 50.39 feet

both scribed 1/16 BT.

T34N R11E

Corner sets approximately 50' east of the C&NW RR.

S498 - 1980

Dated at Rhinelander	, Wis., this 27th	day of March	, 19.80
			0.400

Signature Title Registered Land Surveyor Registration No. S-498 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Langlade , I hereby certify that the within at.....o'clock...... M.

(Register of Deeds)