State of Wisconsin

0	=	Corner	monument	restored.
---	---	--------	----------	-----------

## CERTIFIED LAND CORNER RESTORATION

Index No. C-3

RUSTICK S-2036

APPLETON

History of original corner establishment:

No record of the center of section having been set.

Description of corner evidence found:

Corner was set at the straight line intersection of the 1/4 corners

of Section 6.

Description of monument and accessories I established to perpetuate the original location of this corner Measurements are to the center of bearing trees which are blazed and marked "BT".

NORTH 1/4 LUC CORNER COR CNTR SEC. 6 LANGLADE COUNTY T34N, RHE CORNER Dated at Elcho , Wis., this 20th day of July 19 91 Title Kegis Land Surveyor, Registered Land Surveyor, ox other duly authorized official) instrument was filed in this office for record on the \_\_\_\_\_\_day of \_\_\_\_\_\_\_ (Register of Deeds)