O = Corner monument restored.

CERTIFIED	LAND	CORNER	RESTORATION
		COMB	NESIGNATION

Index No. F-5

History of original corner establishment:

Description of corner evidence found:

No evidence of any corner recovered. Corner established by traverse and computation. Ran traverse from 1/4 corner between sections 7 and 8 to the section corner 5, 6, 7 and 8, bearing N  $4^{\circ}$  48" 33" W, distance 2672.14 feet. Set N 1/16 at 1336.07 feet intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap, stamped: Monument projects 18". Built a rock cairn around base of monument. Marked NBT's -

Sugar 6" S81°W 14.10' Sugar 8" S60°E 22.40' both scribed 1/16 BT.

734N R11E N 1/16 7+8

S498 - 1980

Dated at	Rhinelander	, Wis., this.	18th	day of	April	
Signatur	Kelf (County Surveyor, Registere	Title d Land Surve	Registered	Land Surv y authorized of	reyor Regis	tration No.S-498
Office of Re instrument	gister of Deeds, County of was filed in this office for reco o'clock		Langlade		, I hereby o	ertify that the within
	(Register of Deeds)	·	•••••			
_			_			