

CERTIFIED LAND CORNER RESTORATION

34-11
Index No. J-9

State of Wisconsin }
County of LANGLADE } ss.

History of original corner establishment:

I ROBERT J. POSS, do hereby certify that on the 9TH day of AUGUST, 1970, I found evidence of the SECTION corner of 8-9-16-17 Township 34, North, Range 11 EAST, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:


FOUND IRON PIPE MARKED SET BY C. BORTH ALSO HUGE Y. BIRCH - BUT BLAZES - NO SCRIBE ON OPPOSITE SIDE.

Resident witnesses:


JAMES J. KELLY

Description of monument and accessories I established to perpetuate the original location of this corner.

SET IRON PIPE - PAINTED ORANGE W/ BRASS CAP MKD SEC. COR 8, 9



- 1 = ELM 8 S80E 17.2 T34NR11E
 - 2 = BASSWOOD 10 S35 1/2 E 10.0
 - 3 = HD MAPLE 6 S12 E 21.8'
 - 4 = 30 Y. BIRCH 56 W 5.6 BLAZED ON SW. SIDE.
- THESE TREES BLAZED & SCRIBED NBT



○ = Corner monument restored.

Dated at ELCHO, Wis., this 10TH day of AUGUST, 1970.

Signature Robert J. Poss Title REG. LAND SURVEYOR Registration No. S-0001
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

