O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. *G*-7

History of original corner establishment:

Description of corner evidence found:

No evidence of any corner recovered. Corner established by traverse and computation. Ran traverse from the N 1/4 to the S 1/4 corner and from the W 1/4 to the E 1/4 corner to establish the C 1/4. Corner sets S 1° 47' 43" W, 2572.39' of N 1/4 corner, N 89° 06' 08" W, 2742.37' of E 1/4, N 1° 47' 43" E, 2609.87' of S 1/4 and S 89° 06' 03' E, 2795.63 of W 1/4.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 2-1/2" iron pipe with screw-on brass cap, stamped:

Monument projects 12" above ground.

Marked NBT's -

Cedar 6" S2°E 38.45 feet Cedar 6" S60°W 26.00 feet

Cedar 6" N20°W 26.40' all scribed C 1/4 BT.

T34N R11E $c_{1/4} + 8$

S498 - 1980

hi
ni

(Register of Deeds)