State of Wisconsin

0 =	Corner	monument	restored.
-----	--------	----------	-----------

CERTIFIED LAND COR	RNER RESTORATION	۷
--------------------	------------------	---

Index No. F-6

History of original corner establishment:

Description of corner evidence found:

No evidence of any corner recovered. Corner established by traverse and computation. Computed distance from W 1/16 between 5 and 8 to the WC 1/16, section 8 is 2617.94' at bearing S  $1^{\circ}$  34' 44" E.

Computed location of NW 1/16 is 1308.96, S 1° 34' 96" E of W 1/16 and 1308.98' N 1° 34" 44" W of WC 1/16.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap, stamped:

Monument projects 16" above ground.

Marked NBT's -

Maple 6" S 15° E 18.45'

Maple 6" (cluster) S 64° E 38.33' both scribed 1/16 BT.

T34N R11E

S498 - 1980

Dated at Rhinelander	, Wis., this.	18th	day o	f Ap	ril , 19 80
Signature Liles I Sla 11.41.1.	Title	Registered	Land St	urveyor	Registration No. S-498
(County Surveyor, Registered	d Land Surve	eyor, or other dul	ly authorize	d official)	
Office of Register of Deeds, County of		Langlade		·····,	I hereby certify that the within
instrument was filed in this office for reco	rd on the		da	y of	, 19
ato'clock M.					
(Register of Deeds)	······	••••••	· <b>·</b>		