U. S. PUBLIC LAND SURVEY MONUMENT RECORD


INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.

This corner was originally set by William E. Daugherty and was perpetuated by Robert J. Poss in 1969.




(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

We re-tied this corner to perpetuate its location and to make it easier to locate for future users. We accessed this corner via a field entrance along C.T.H "K" in Section 10.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)

 Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.



Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

NA	
~///	

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.?

2)

(g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

(i) I, DAN HIGGINBOTHAM


(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Signature

1-10-95

Date




State of Wisconsin
County of LANGLADE ss.
I KOBERT J. Foss , do hereby certify that on the day
of June 1969., I found
evidence of the 1/4 SEC.
corner of SECS. 10£ 15
Township, North, Range
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.
Resident witnesses:
Resident witnesses.
JEG10
]
#_ SEC! 15 +
]
1 1 1

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

94-11 Index No. (T-/-

History of original corner establishment:



Description of corner evidence found:

FOUND IRON PIPE & BLAZED TREES.
FOUND ORIGINAL STAKE BESIDE STAKE
BURIED IT ALONG SIDE

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 1/2" IRON BRASS CAP	POST MKD 1/4 COR	ALL TREES WITH OLD BLAZES,
	SEC.10 SEC.1S T34N RILE	C) 1. W. BIRCH & NZ9E 13.8 2. HD. MAPLE 8 N74E 15.2
OLO FENCE	@_ /· 5	3. ASPEN 2055/4E 9.9. CQ Z 4 BALSAM 18 S83%W 37.0
	G 3	

Dated at ZZZZZZ	Wis., this	14	day of	~	1963
Signature (County Surveyor, Regis	Title Rec	LAND or other duly a	Surveyor authorized official)	Registration	n No. S-000)
Office of Register of Deeds, County o instrument was filed in this office for rat					
(Pagistor of Da	ads)	•••••			

.....Deput