

CERTIFIED LAND CORNER RESTORATION

34-11

Index No. J-14

State of Wisconsin }
County of LANGLADE, } ss.


I, ROBERT J. POSS, do hereby certify that on the 14TH day of JULY, 1969, I found evidence of the WEST 1/16 corner of SECS. 10 & 15 Township 34, North, Range 11 EAST, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

History of original corner establishment:

Description of corner evidence found:

FOUND IRON PIPE & BLAZED TREES




Description of monument and accessories I established to perpetuate the original location of this corner.

SET 1 1/4" PIPE WITH GALV. CAP
NKD. WEST 1/16
SEC. 10
SEC. 15



- 1= RED OAK 10N 20E 27.0
- 2= BALSAM (OLD SCRIBE MK) 3S 81 1/2 E 8.0
- 3= BALSAM 6" S 5 1/2 E 25.5
- 4= MAPLE (OLD BLAZE) 6 S 10 E 46.0
- 5= W. BIRCH (OLD BLAZE) 10N 41W 6.5



Dated at ELCHO, Wis., this 14TH day of JUNE, 1969.

Signature Robert J. Poss Title REG. LAND SURVEYOR Registration No. S-0001
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

○ = Corner monument restored.

FORM 985 N. C. MILLER CO., MILWAUKEE