County of	. AT. C. V. V. S. C.	·/		
WILLIAM				,
ertify that	on the			/ <b>5</b> da
f JA vidence of	NUAR	N // Q	, 19. <b>7.6</b>	, I foun
orner of	tne SECT	70NS	14 &	
Cownship	34	7		orth, Rang
	,	Fourth	Principa	l Meridiai
s described				
establishe				
s described ocation of t			etuate t	ne origina
cation or t	ins corne			
Resident wi	tnesses:			
n	O	ı .		
K	Bul		n	
	T34K	1- R 1/	E	
	i I	l I	1	
	I	i	i	
	I	1	1	
	<u> </u>	-!	+	
		•	•	
	I	1	1	
	 	1 1	1	

State of Wisconsin

O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION


Index No. K - 21

History of original corner establishment:

see M. Hutchinson's Notes of May 20, 1914

Description of corner evidence found:

OLD BEARING TREES LOCATED.



Description of monument and accessories I established to perpetuate the original location of this corner.

| 18" JACK PINE | 18" TACK PINE - OLD BEARING
| TREE MARKED AT BACE | 112" TREE MARKED AT BASE WITH SECT BLAZE MARKS. T34N RIIE 15 JAN 76 SET 1/2 B.I.P. WITH BRASS CAP MARKED: -2 WFK SET N'/B CORNER SECT 14/13-T. 33N.-R.IIE. FROM CONTROL SURVEY OF SECTION 14 AND OLD BEARING TREES LOCATED. NBT 10" JACK PINE + AT RASE. NBT 20" JACK PINE + AT BASE ELCHO, Wis, this 15 Mday of JANUARY, 1976... Dated at..... Title REGISTERED LAND SURVEYOR Registration No. 51098 (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of......, I hereby certify that the within at.....o'clock...... M. (Register of Deeds) By......Deputy