U. S. PUBLIC LAND SURVEY MONUMENT RECORD


INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.


This corner was originally set by William E. Daugherty and was perpetuated by Robert J. Poss in 1968.



(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

We re-tied this corner to perpetuate its location and to make it easier to locate for future users. This corner is located near a garden along the edge of a definite occupation line.

(c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.) Describe witness monuments.



Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.? (f)

2/


Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions (g & h) and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

HIGGINBOTHAM

(type or print name)

certify that the corner location shown on this record was determined by me or under $my\ direction\ and\ control\ and\ that\ this\ U.S.\ Public\ Land\ Survey\ Monument\ Record\ is$ correct and complete to the best of my knowledge and belief.

1-10-95



		CERTIF
of JUNE	ADE SS. Poss	History of o
Township, Fo as described hereon; and I established a new mo	, North, Range urth, Principal Meridian, I that from this evidence onument and accessories perpetuate the original	Description
Resident witnesses:		
		Description
	sec./4	Mag.
		Dated at
	[Signature
SE ¢.22	SEQ 23.	Office of Reginstrument v
1		***************************************

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

ROBERT

POSS
S-0001
ELCHO, WISCONERN

SURVE

Description of corner evidence found:

FOUND RAILROAD IRON IN UPRIGHT POSITION.

ALSO FOUND B.T'S MARKED BY PREVIOUS

SURVEYOR

Description of monument and accessories I established to perpetuate the original location of this corner.

, kosp	* /50'+	WOODS	B
Ø2. 78	CULT.	.1-0	Ç

1. OLD BT. W/MARK SEC.14
SUGARIA N314 T.5'

2. OLD BT. W/MARK SEC.14

SUGAR 16 N63'ZE 16.7F;

WOODS 3. NEW BT MKD NBT

SUGAR 225693/4 EGZAFT

I = RAILROAD IRON

O : BRASS CAP IN CONC.

MKD SECTOR SEC. 23

SEC. 23 SEC. 23

T34N R II E.

1968.

Signature County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of , I hereby certify that the within

strument was filed in this office for record on the day of M.

(Register of Deeds)

By.....Deputy