U. S. PUBLIC LAND SURVEY MONUMENT RECORD


INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.


This corner was originally set by William E. Daugherty and was perpetuated by Robert J. Poss in 1968.



(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

We re-tied this corner to perpetuate its location and to make it easier to locate for future users. This garage is believed to be located on Lot 16 Burton's Woods @ N11300 Woodland Lane.

(c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.) Describe witness monuments



Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

NA

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.?

2)

(g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

(i) I, DAN HIGGINBOTHAM

(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Lan fremboth

1-10-95

Affix Land Surveyor Seal

HIGGINBOTHAM

BIRNAMWOOD

Date

		Index No
State of Wisconsin	History of original corner establishment:	manus A. P.
County of Langlade, ss.	ORIG ASPEN, 10, 560 E 14 \$ ASPEN 10 565W 39	SCONO III
· ^	11216 13461, 10, 2606 11 4 1121614 14 24	W. C. W.
I, Robert J. Foss., do hereby certify that on the 18 th day	BROOKS FE97-104 1901 COULON'T FIND COR, SOT COR	ROBERT .
of May , 19.68., I found	MARKUD NEW BT NORWAY, 12, N 15/2E, 33/4 (2195')	# . Dog . # .
evidence of the 1/4	LOOKS LIKE POSS FOUND BROOKS CORNUM & NORWAY BT	POSS 5-0001
corner of between Sections 145/5 Township 34, North, Range	D. Theaty 6/94	ELCHO, WISCONSIN
North, Range , North, Principal Meridian,		1 P1:
as described hereon; and that from this evidence	Description of corner evidence found:	MIND SURVE
I established a new monument and accessories	Found Stake wired to an Iron pipe, Stake badly ro	
as described hereon to perpetuate the original location of this corner.	identified pipe as placed by him to preserve the corner	location. Found two BJs.
100au 01 and 03 110 1		
Resident witnesses:		
	Description of monument and accessories I established to perpetuate the original	location of this corner.
	දිා	Brass Cop MKd.
	R. Ook 14N3IW 19.8	1/4 Con
	·	
	Scribe Mks Visible	Sec./4
	Oriq. B.T. Scribe Mks. Visible Scars not healed. Prob. Orig. W.Birch Orig. B.T. Prob. Orig. W.Birch Orig. B.T. Scars not healed. N'Way Pine 26 NBZE 26 B.T. D.S. S.Z. W.R. Off ORIG. B.T. OS S.Z. W.R. Off ORIG. B.T. ORIG. B.T. OS S.Z. W.R. Off ORIG. B.T. OS S.Z	Sec.15. Sec.14
 	8.1. 10552W 8.0fl C3R.Dak 10514E 37.9	
	10352W 8.011 E J OUR 10014E 31.5	Trees blazed & Marked NBT.
	Dated at £LCHO, Wis., this 18 th day of	• •
	\wedge 1	·
ان ا	Signature County Streeyor, Registered Land Survey or October duly authorized official	Registration No.5-/
	Office of Register of Deeds, County ofday ofday ofday of	, I hereby tertify that the within
	ato'clock	, =2
	(Register of Deeds)	

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

34-11

Index No.

27 R. Oak 14N3IW 19.8	Br	-083 Cop MKd. 1/4 Con
Prob. Origi W.Birch B.I. 10552W 8.0ft	Oriq. B.T. Scribe Mks. Visible Scars not heoled. N'Way Pine 26 N8ZE 20.0'	Sec.IS. Sec.IA
B.I. 10552W 8.0ff	63R. Dak 10814E 37.9	Trees blazed Marked NBT.

(Register of Deeds)