location of this corner.

Resident witnesses:

T34N-RILE					
	] 	 	] 		
	!				
	<b>.</b>	 	l 1		
	<del>-</del> 2	¦-(			
	· [	' !			
	 <del> </del>	! !	 <del> -</del>		
	l I	! !	) 		
	l I	 	 		
	ı	l	l		

O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION


Index No. *N* - 12

History of original corner establishment:

Description of corner evidence found:

Broken ass AT GROUND LEVEL.
FOUND TWO OLD BEARING TREES

SET 1/2+42" IRON PIPE WITH BRASS CAP. MARKED BEARING TREES



Description of monument and accessories I established to perpetuate the original location of this corner.

2 4	P.K. NAIL  Dated at ELCHO  Wis., this. 27	GRASS CAP  MARKED SESCOR  CORNER IS  LOCATED ON  HIGH LAND ON  EDGE OF SPRUCE  + CEPAR SWAMP  MARKED  SECT 21  T34 NR IIE  9-27-79  WEK  day of SEPTEMBER 1979
	Signature Welliam 5- Kelly Title County  (County Surveyor, Registered Land Surveyor, or other du	SURUEYOR Registration No.5-1098 ly authorized official)
	Office of Register of Deeds, County ofinstrument was filed in this office for record on the	, I hereby certify that the within day of, 19, 19
	(Register of Deeds)	···
	Deput	17