State of Wisconsin

SS.


0 =	- Corner	monument	restored.
-----	----------	----------	-----------

CERTIFIED LAND CORNER RESTORATION

Index No. 14-7

History of original corner establishment:

Description of corner evidence found:



Description of monument and accessories I established to perpetuate the original location of this corner.

SET N'IB CORNER ON N-5 LINE SECT. 17 T.34N.-R. IIE.

N 14" WHITE ASH 8" BASS WOOD N 77°W-10.15') N 77°W-10.15')	17 AND THE NY4 COR. : WITH BRASS CAP AND I	RUN BETWEEN THE CENTER SECTION SECTION 17. SET 1/2" IRON PIPE MARKED NEW WITNESS TREES. WITNESS TREES MARKED:) T 34N-RIIE
SS OF THE BASSWOOD		SEC 17 10-10-77 N-5 1/4 LINE
Dated at ELCHO, \	Vis., this	
Signature William J. Helly (County Surveyor, Registered	Title RESERVED LAND SUR	VEYOR Registration No. 51098
Office of Register of Deeds, County of instrument was filed in this office for record ato'clock		, I hereby certify that the within
(Register of Deeds)		