
State of Wisconsin } ss	
County of LANGLADE	j.
of November 19.75, 19.7	Range eridian, vidence essories
location of this corner.	
Resident witnesses:	
J. DREW	<del>-</del>
T. 34 N. R. II.E	
1 1 1	
i i i	
+	
	ŀ

State County of	of Wisc		ss.	
certify that of Nove evidence of corner of	on the	1977   1977   19.7   SECTION   18 ‡ 17   urth Princip   that from tonument and	Jorth, Range al Meridian, this evidence d accessories the original	
Resident wi	tnesses:			
J. D.	ZEW			
	•••••			t
	T. 34 N.	R.II.E		4
	 	; ! ! '		
	i — — — — — — — — — — — — — — — — — — —			
<b>3</b>	-    -	¦ <b>∸∫</b> I		
	  -	 		
- <b></b>	<u> </u>	-		
	!	]   		

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION History of original corner establishment:

ORIGINAL WITNESS CORNER SET BY C. BORTH,



Description of corner evidence found:

LOCATED 2" I.P. IDENTIFIED BY RESIDENT WITNESS AS A WITNESS TO CORNER IN ROADWAY. DRIGINAL STONE IN ROAD GRADED OUT.

7/94 BALSAM CUT OFF BY LOCGER BY MISTAKE. Description of monument and accessories I established to perpetuate the original location of this corner. SET I" PIRE ON CORNER FROM + AT BASE. WIT. PIPE AND SET 2" B.T.P. WITH BRASS CAP AS A WIT. TO CORNER. BRASS CAP POWER POLE MARKED -FENCE LINE O 2" I.P. FOUND IN PLACE 1/4 SECT T I"GALV. I.P. 6" UNDER ROAD T. 34 N- RIIE SURFACE. COR 22 FTE "I.P. WITH BRASS CAP. WITNESS CORNER NBT- 12" WHITE BIRCH-CB+ AT BASE day of NO ....., Wis., this 197H NOVEMBER 19 75 ELLHO Signature William J. Kolles Title REGISTERED LAND SURVEYOR Registration No. S. 1098 (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of....., I hereby certify that the within at......o'clock...... M. (Register of Deeds)