as described hereon to perpetuate the original

Resident	witnesses
IX CSICICITE	WILLESSES

location of this corner.


H. Wy	right	
	J	

T 3	4N-	RILE	
	 	l 	I
 	 	 -	1
	1 ! !	1 	I I 1
[2	-3 	
	! !] 	
	1017.53	:	
	l !	 	l !

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:



Description of corner evidence found:

I.P. SET ON CONTROL SURVEY FOR LAND SUBDIVISION

NOTE: NBT BLAZED & SCRIBED NBT CHEST HIGH AND MARKED WITH A + AT BASE

Description of monument and accessories I established to perpetuate the original location of this corner. SET 2" BIP WITH BRASS CAP MARKED

S LINE	Tan	14"OAK	NBT - 6"WHITE	BIRCH
FOUT LOT 2	N87°13'24"W	6.35 W NOOFE	51.5 ' 587°13' 24"E	LOWER POST LAKE
T34N RILE WEK	1017,53' To 54 th COR. 5 BCT 23	2'17	8° €	((c
Dated at ELCHO	, Wis., this3	day of NOVE	MBER NBT	6" B BIRCH 9.74.
Signature Milliam 1. (County Surveyor	Registered Land Surveyor, or oth	and Surveyor cr duly authorized official)	Registration No. \$	-1098
Office of Register of Deeds, Couinstrument was filed in this officat	e for record on the	day of	hereby certify that the	within 19
(Registe	er of Deeds)			

..Deputy