


CERTIFIED LAND CORNER RESTORATION

Index No. U-1

34-11

State of Wisconsin }  
County of Langlade } ss.

History of original corner establishment:  
No evidence of any previous corner.




I, Daniel K. Plegger, do hereby certify that on the 20th day of November, 1980, I ~~found~~ established ~~xxxxxx~~ of the S 1/16 corner of sections 25 and 30 Township 34, North, Range 10 & 11 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.


Description of corner evidence found:  
Ran traverse from section corner 25-30 and 31-36 T34N R10 & 11E to 1/4 corner between sections 25 and 30 for a distance of 2637.979 feet at bearing N 1-24-36E.  
Set S 1/16 corner 1318.99 feet intermediate.

Resident witnesses:  
.....  
.....  
.....

Description of monument and accessories I established to perpetuate the original location of this corner.  
Set a 1" x 18" iron pipe on the west side of Summit Lake Drive for true corner.  
Set a 1-1/2" I.D. iron pipe with screw-on brass cap 40 feet east for witness corner - stamped:  
Projecting 18" above ground.  
Marked NBT's to true corner:  
Sugar 7" S79°E 43.93 feet  
Maple 6" S42°W 30.00 feet  
scribed 1/16 BT



FORM 987 W. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 4th day of February, 1981

Signature Daniel K. Plegger Title Registered Land Surveyor Registration No. 1537  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....  
(Register of Deeds)

By..... Deputy