CEDTICIED	LAND	CODNED	RESTORATION
CERTIFIED	LAND	CORNER	RESTURATION

History of original corner establishment:

Index	No	ν	5
HILLOCA	110		

tate	ΟŢ	Wisconsin	i
			} ss.
_	Τ.	1 -do	55.

Langlade County of.....

I Philip T. Hansen certify that on the 30th day of January , 19 76 , I found evidence of the Section corner of Sections 29, 30, 31, and 32 Township......34 , North, Range ll East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

	CON
Resident witnesses:	S
Glen Barker	PHILIP T. V
Jim Claflin	が HANGEN は 対 ARGONNE, 資料
Herb Wagoner	VIS. 5-498 3 Q- A
	NO CHOVE
ma I N	No O IT WAS A STATE OF THE PARTY OF THE PART

	T34N R11	LE	
1	1	I	
1	1	1	l
	1	1	
	- - i-	- - ₁	
] ;	1	i i	}
!	s	30	
		 	
'	1	' 	
!	1	1	
 	·¦·		
'	 	I I	sc
		21.465	
			22.403

Corner monument restored.

Description of corner evidence found: Recovered Chas. Borth's 6" cedar post, squared and scribed Sec. 29, S30, S31, S32 in poor condition. An old sleigh runner had been driven on the side and wired to the cedar post. An original pine stump recovered N24°E, 10 1ks. (9.7 1ks.), scribed S29, T34N, R11E was recovered. This stump still in fair condition.

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced 6" wood post with 2-1/2" iron pipe with cap stamped -Pipe projects 20 inches above ground. NBT's - Hemlock 7" N30°W 18.4 1ks. scribed SC BT S51^OW Hemlock 11" 14.4 lks. scribed SC BT N71⁰E Hemlock 10" 20.6 lks. scribed SC BT

CPI-1976

S498

T34N, R11E

Dated at Rhinelander Wis. this 16th day of February 19 76

Signature Mulip Thanselv: Title Registered Land Surveyor Registration No. S-498 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Langlade , I hereby certify that the within at o'clock M.

(Register of Deeds)