

CERTIFIED LAND CORNER RESTORATION

Index No. 213

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

I Philip T. Hansen, do hereby certify that on the 18th day of February, 19 76, ~~found~~ established evidence of the SC-1/16 corner of Section 30 Township 34, North, Range 11 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found: Corner established from previously established C-1/4 corner and South 1/4 corner. Distance from C-1/4 corner to S-1/4 is 39.84 chains, bearing S0°24'E.

Set SC-1/16 corner on true line N0°24'W, 19.92 chains from South 1/4 corner and 59.72 chains S0°24'E of N-1/4 corner

Resident witnesses:

Glen Barker

Jim Claflin

Herb Wagoner



Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 2" iron pipe with brass cap for corner. Cap stamped - Pipe projects 18" above ground.


S498
T34N, R11E

NBT's - Sugar 10" S73°W 3.603 chains scribed 1/16 BT
Hemlock 18" S42°W 3.802 chains scribed 1/16 BT

S 30
SC-1/16
CPI - 1976

Pipe and BT's painted blue.
Corner sets on the south edge of an old field.

FORM 985 Wisconsin Planning Advisory Co. Milwaukee, Wisconsin



○ = Corner monument restored.

Dated at Rhineland, Wis., this 4th day of March, 19 76

Signature Philip T. Hansen Title Registered Land Surveyor Registration No. S-498
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Langlade, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy g