## O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

Index No. **X**- **3** 2

History of original corner establishment:

No records of any previous survey.

Description of corner evidence found:

No evidence of any corner recovered.

Established corner by running traverse from C 1/4 corner to recovered EC 1/16 corner. Computed distance 21.59 chains at bearing N  $87^{\circ}$  56' 45" E. Ran true line S  $87^{\circ}$  56' 45" W a distance of 21.59 chains and set WC 1/16 corner.

Description of monument and accessories I established to perpetuate the original location of this corner. Set 2" iron pipe with brass cap projecting 18" above ground, cap stamped:

Marked NBTs - Sugar 10" N20°E, 51.2 links, scribed 1/16 BT. Sugar 6" S64°E, 16.8 links, scribed 1/16 BT.

T34N R11E WC  $1/16 + \frac{3}{1}$ S498-1977

Wis., this 21st day of September , 19.77 Rhinelander Dated at. Title Registered Land Surveyor Registration No. S-498 Signature: (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of Langlade , I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_\_day of \_\_\_\_\_\_\_, 19\_\_\_\_\_\_ at.....o'clock...... M.

(Register of Deeds)