State of Wisconsin					
County of LANGLADE ss.					
I. WILLIAM F. KELLY, do hereby certify that on the day of day of 19.77, I found evidence of the SECTION corner of SECTION 35, 36, 2 \$ / Township 3, \$ 33, \$ 36, 2 \$ / Township 5, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories					
as described hereon to perpetuate the original location of this corner. Resident witnesses:					
T. 33NR. II E .					

	T. 33N	R.IIE.	
Ψ	l	<u> </u> 	
	I	I	1
	! !	l I	
	i i	; _ ;	
	! [! 	'
	l	1	 -
	- -	/	
1	! !) 	'
İ]	1	l
	 	¦	<u>-</u>
	l I	ļ	
	I		!
	<u> </u>		

O = Corner monument restored.

CERTIFIED	LAND	CORNER	RESTORATIO	N
JEN 1 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		COMMEN	NEGIONATIO	

History of original corner establishment: '
SECTION CORNER SET IN 1930'S ON RESURVEY.

KELLY S1098 ELCHO,

Description of corner evidence found:

LOCATED SECTION CORNER MONUMENT. MONUMENT HAD BEEN DAMAGED ! BRASS CAP BROKEN OFF. MONUMENT WAS TILTED OFF AT AN ANGLE.

· · · · · · · · · · · · · · · · · · ·	sories I established to 	perpetuate the original lo	ocation of this corner.
4" WHITE BIRCH 1973	SET NEW /BRASS CAP I	IMH BRASS CAP MARKE 1/2" × 42" IRON PIPE V FROM WITHESS TREES	2
Dated at ELCA	3 <i>IRCH</i> ∀0 .Wisthis	/ST day of	OCTOBER, 1977
Signature William K. Kell	4 Title 256 75		Registration No. 51098
Office of Register of Deeds, County instrument was filed in this office for at	ofr record on the	day of	, I hereby certify that the withi
(Register of	Deeds)		

I WILLIAM F. KELLY , do hereby certify that on the , 19 82 , I found evidence of the , 55

evidence of the SE corner of SECT. 35

Township 34, North, Range 11 EAST. Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original

location of this corner.

Resident witnesses:

T34N. RIIE				
	l I		I	
		 	! !	
	!		 •	
	! !		, 	
	¦3	- 5	<u> </u>	
	l 1	 	i !	
	i ! 1 !	 -	l <u>'</u>	
	i — — — i	i I	! !	
	t I	 	! !	
	1	!	<u> </u>	

O = Corner monument restored.

History of original corner establishment:


ORIGINAL CORNER ESTABLISHED BY
WILLIAM DAUGHERTY IN JULY, 1859.

Description of corner evidence found:


1/2 Brass CAP MONUMENT,

FOUND IN PLACE, WITH 2

EXISTING BTS. MARKED INEW BT.



Description of monument and accessories I established to perpetuate the original location of this corner.



Dated at	ELCHO	, Wis., this	74	day of	APRIL	, 19 <u>8</u> 2.
Signature?	Wleam or.	Kolley Title	COUNTY reyor, or other du	SURVEYOR ly authorized official)	Registration	No. 1098
instrument w	ister of Deeds, Cou	e for record on the.			., I hereby certify t	hat the within
•••••	(Regist)	er of Deeds)		•••		