

CERTIFIED LAND CORNER RESTORATION

34-11

Index No. X-Y-23

State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 23rd day of May, 1970, I found evidence of the MC corner of Section 36 Township 34, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

This corner set in the platting of Perch Lake in the 1950's

Description of corner evidence found:

Found iron pipe, stake down,
Old BT White Birch 8" ϕ Ft. 6 inches


Resident witnesses:

J. Kraska
J. Weiss

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 4" brass cap in cement
New B.T.
White Birch 10" S72E 13 Ft.
B.T.'s faced at base of tree and scribed BT.

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.



Dated at Antigo, Wis., this 23rd day of May, 1970

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy