

CERTIFIED LAND CORNER RESTORATION

34-11

Index No. W-X-23


State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 23rd day of May, 19 70, I found evidence of the MC corner of Section 36 Township 34, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

J. Weis
J. Kruppa

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

This corner set in the platting of perch lake in the 1950's

Description of corner evidence found:

Found old stake down, marks not plain,
Old B.T.'S

White Birch 8" S53E 6 Ft. 3 inches
White Birch 6" N8W 21 Ft. 3 inches


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 4" brass cap in cement.

New B.T.'s

Hard maple 8" ~~XXXXXXXXXXXXXXXXXXXX~~ N2E 36 Ft. 2 inches
Red maple 5" N47W 16 Ft. 8 inches

B.T.'s faced at base of tree and scribed BT.



Dated at Antigo, Wis., this 23rd day of May, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy