ERTIFIED LAND CORNER RESTORATI				
FRIEFL LAWL CURIVER RESILIRALI	COTICICO			
		IANI	LURINER	RESIDRAIN

Index No. B- 24

History of original corner establishment:

Description of corner evidence found:

P. Hausen on Previous survey

(Register of Deeds)

WILLIAM F.

KELLY

S1098
ELCHO,
WIS.

VID SURVEYOR

MILLIAM F.

KELLY

S1098
ELCHO,
WIS.

SET 1/4' & 42' BLACK /RON PIDE WITH BRASS CAP MONUMENT.

Description of monument and accessories I established to perpetuate the original location of this corner.

-	-		
_	-		

0 =	Corner	monument	restored.
-----	--------	----------	-----------

State of Wisconsin

County of LANGLADE

location of this corner.

Resident witnesses:

I WILLIAM F. KELLY , do hereby certify that on the 26th day of ULY , 19 B. I found evidence of the NE 1/16

corner of SECTION !

Township.........., North, Range

, Fourth Principal Meridian, as described hereon; and that from this evidence

I established a new monument and accessories as described hereon to perpetuate the original

T33N, RQE

4		Q	1.		NE 1/16 Co	DR \
	ALL BT'S NEW	đ	8 2	8 MAPLE	SECT 1	
	\		N61.	0'	T33N + 1	R 12€
HAR	(89)		3/0	-/"4" BRASS CAF	8-26-8	31
ş	PK & RIBBON		2/8	MONUMENT		. /
	/ 1		SO B"MAPLE		WFK	
Dated	at ELCHO	., Wis., this	26∄	day of	JULY	, 19 B I
Signat	ure Mlleam J. Kell (County Surveyor, Registere	Title		SURVEYOR		No. 1098
Office	of Register of Deeds, County of	•			•	that the within
	ment was filed in this office for reco					
	o'clock M.					•
						_