State of Wisconsin

CERTIFIED LAND CORNER RESTORATION


Index No. F - 17

History of original corner establishment:

Description of corner evidence found:

Found remains of old 4 mg seribed POST AND ONE OLD BEARING TREE

SET I'L + 42" IP WITH BRASS CAP AND MARKED WIT COR.



Description of monument and accessories I established to perpetuate the original location of this corner. BEARING TREES B' (EDAR SMARKED SECT SPRUCE SWAMPY 10 +11 AREA. T34NR 12E 9-11-79 Dated at ELCHO, Wis., this 16 and day of SEPTEMBER, 1978 Signature Welleam 5 Kelly Title COUNTY SURVEYOR Registration No.5-1098
(County Surveyor, Registered Land Surveyor, or other duly authorized official) (Register of Deeds)