

CERTIFIED LAND CORNER RESTORATION

34-12  
Index No. N-25

State of Wisconsin }  
County of Langlade } ss.

History of original corner establishment:

I Raymond J. Hallisy do hereby certify that on the 5th day of Sept., 19 70, I found evidence of the Section corner of 13, 18, 24, & 19 Township 34, North, Range 12 & 13, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found squared stake standing marked 24, 13, 18, 19  
1" ~~XXX~~ iron pipe along side.


Resident witnesses:

.....  
.....  
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock bound.

Now P.T.'s  
Hard Maple 6" N1E 15 Ft. 3 Inches  
Hard Maple 6" S19E 32 Ft. 11 Inches  
P.T.'s faced at base of tree and scribed PT.



FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 5th day of Sept., 19 70

Signature [Signature] Title Reg. Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....  
(Register of Deeds)

By..... Deputy