				ر عن.
County	of LANG	LAUE		J
certify to of	hat on the August. of the Sip. 34 bed hereorished a ne	N 19 FOURTH T; and that w monument to per	, 19, N Princip t from t	Jorth, Range al Meridian, this evidence the original
			petuate	the original
Residen	t witnesses	: :		
		N, RI	Q.E	
	1	1		l -
	1	1		I

O = Corner monument restored.

State of Wisconsin

SS.

CERTIFIED LAND CORNER RESTORATION

Index No. N-19


History of original corner establishment:

ORIGINAL CORNER ESTABUSHED BY J. NOWLIEN IN MAY OF 1865.

Description of corner evidence found:

LOCATED CORNER SET BY T. ARNOTT, R.L.S. 5887

2" IRON PIPE WITH BRASS CAP MONUMENT MARKED NEW WITHESS TREES.



Description of monument and accessories I established to perpetuate the original location of this corner.

J	NEW BT'S MARKED		() () () () () () () () () ()	12" BALSAM	Is Located	734N, R	2 €
Mark	Pk Naik	8'Balsam 361eV	20 0 m	ON EDGE OF 2" IRON PIPE NOSEN	WET BOG	Sec. 1 1/4 Sec. 5887	Cor 23
Dated at	ELCHO	, Wis., this		day of	AUGUST	, 1	9.80
Signature.	Mllam S. Ku (County Surveyor, Reg	Title	COUNTY or, or other duly	SURVEY authorized office	OR Re	gistration Nol	298
instrument	egister of Deeds, County was filed in this office for o'clock	ofrecord on the		day of.	, I hereby	y certify that the	e within 19
	(Register of I	Deeds)					