

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }
County of Lan glade } ss.

History of original corner establishment:

Set by C. Borth in the 1930's

I Raymond J. Hallisy do hereby certify that on the 13th day of June, 19 71, I found evidence of the Section corner of Section 16, 15, 21, & 22 Township 34, North, Range 12E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found large wood post BT's
19" White Pine N68E 19.5 Ft.
23" White Pine N65W 51.5 Ft.



Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap in cement, rock mound.

BT'S to Corner
7" Hard Maple S70W 12 Feet
6" Red Maple N49W 21 Feet 3 inches
BT's faced at base of tree and scribed BT.



○ = Corner monument restored.

Dated at Antigo, Wis., this 13th day of June, 19 71

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 1685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy

FORM 985 K. C. MILLER CO., MILWAUKEE