

CERTIFIED LAND CORNER RESTORATION

Index No. 15-13

State of Wisconsin }
County of LANGHADE } ss.

I, RAYMOND J. HALLISY, do hereby certify that on the 13 day of SEPTEMBER, 1980, I found evidence of the NORTH 1/4 corner of SEC. 16 Township 34N, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

History of original corner establishment:


1930's RESURVEY PROJECT OF W 1/2 T34N R12E
C. BORTH

Description of corner evidence found:


6" SQUARED WOOD POST - POST BROKEN FROM WINDFALL TREES
CORNER POINT IN PLACE
NO B.T.S SCRIBED 1/8

Description of monument and accessories I established to perpetuate the original location of this corner.

REPLACE WOOD POST WITH 2" IRON PIPE WITH BRASS CAP - CORNER POINT AND POST TOP BESIDE IRON PIPE



BTS - NEW CEDAR 6" N32°E 12'-2"
CEDAR - 6" - N61°W 14'-9"
CEDAR 6" - S19°W 15'-5"
BTS SCRIBED ON BOTTOM FACE



○ = Corner monument restored.

Dated at AWAUGO, Wis., this 13 day of SEPTEMBER, 191980

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy