

CERTIFIED LAND CORNER RESTORATION

34-12 Index No. N-4


State of Wisconsin }  
County of LANSHIRE } ss.

I RAYMOND J. HALLISY, do hereby certify that on the 14 day of JULY, 1973, I found evidence of the E 1/4 (18-19) corner of BETWEEN Sec 18-19 Township 34, North, Range 12 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

1930 RESURVEY (C. BORTH)

Description of corner evidence found:

WOOD POST - METAL LOCATION POSTER WITH NAIL MARKING CORNER LOCATION

OLD BT PJ 14" N57E 67'4"

Description of monument and accessories I established to perpetuate the original location of this corner.

1/2" IRON PIPE WITH BRASS CAP

NEW BT PN 9" S32W 12'7"



Dated at ANTIGO, Wis., this 14 day of JULY, 1973

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

\_\_\_\_\_  
(Register of Deeds)  
By \_\_\_\_\_ Deputy